David McCandless

- 1 A. I don't know if I can put absolute numbers on it.
- 2 | Q. I'm not asking you to put numbers on it.
- A. Well, to say that it's more or less, though, in my
- 4 mind, I have to put a number on it.
- 5 | Q. Okay.

8

9

13

14

15

16

17

20

21

22

23

24

- 6 A. How can I say more or less without assigning a percentage?
 - Q. well, I'm not asking you how much more or how much less.
- 10 A. They're both plausible scenarios.
- Q. Okay. And you can't tell me as you sit here now which scenario is more plausible than the other?
 - A. Given the information I have, I don't know that I can.
 - Q. Okay. Well, in 2007 in your report you state -- and I'll just direct you to page 6, conclusion 2.

 And if you could read that to me.
- 18 A. Number two?
- 19 | Q. Yes.
 - A. "The 8Y1 hydraulic manifold was located at the rear of the cab near the hydraulic reservoir. The hose connection that supplied the cooling fan separated at the manifold allowing a release of pressurized hydraulic fluid into the engine